2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

City of Sacramento

Magpie Creek Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	Α
	Operation & Maintenance Manual	А
	Plant Building	А
	Communications	А
	Safety	М
	Cranes	А
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	А
	Sluice / Slide Gates	А
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 1 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Reclamation District No. 2063

Reclamation District No. 2063 Pumping Plant (Nelson Drain)

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	U
	Operation & Maintenance Manual	U
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	U
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 2 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Reclamation District No. 2096

Wetherbee Lake Pumping Plant & Navigation Gate

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	U
	Operation & Maintenance Manual	U
	Plant Building	Α
	Communications	Α
	Safety	М
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	М
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α

Monday, April 13, 2009 14:52 Page 3 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Sacramento County

American River Pumping Plant No. 1 Howe Avenue Storm Drain D - 05

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

American River Pumping Plant No. 2 Willhaggin Storm Drain D - 43

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 4 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

San Joaquin County Flood Control District

Mormon Slough Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	U
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Mormon Slough Pumping Plant No. 2

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	U
	Operation & Maintenance Manual	Α
	Plant Building	М
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 5 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

San Joaquin County Flood Control District (cont.)

Mormon Slough Pumping Plant No. 3

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	U
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	Α
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	М
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 6 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Sutter Maintenance Yard

Middle Creek Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
M	Operating Log	U
	Operation & Maintenance Manual	U
	Plant Building	М
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	М
	Power	Α
	Motors, Engines, Fans & Gear Reducers	М
	Pump Control Systems	М
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	М
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Sutter Bypass Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
Α	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	М
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 7 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Sutter Maintenance Yard (cont.)

Sutter Bypass Pumping Plant No. 2

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	U
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	М
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Sutter Bypass Pumping Plant No. 3

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	Α
	Pump Control Systems	M
	Sumps/Wet Well	Α
	Trash Racks	Α
	Trash Rakes	Α
	Sluice / Slide Gates	Α
	Electric Gate Operators	Α
	Manual Gate Operators	Α
	Other Metallic Items	Α
	Flap Gates	Α
	Closure Structures	А
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 8 of 9

2008 Pumping Plant Summary Report

Overall Unit and Item Ratings

Turlock Irrigation District--Formerly LD0023

Gomes Lake Pumping Plant

Overall Unit Rating	Rated Item	Item Rating
A	Operating Log	Α
	Operation & Maintenance Manual	Α
	Plant Building	Α
	Communications	Α
	Safety	Α
	Cranes	Α
	Pumps	Α
	Power	Α
	Motors, Engines, Fans & Gear Reducers	А
	Pump Control Systems	Α
	Sumps/Wet Well	А
	Trash Racks	Α
	Trash Rakes	А
	Sluice / Slide Gates	А
	Electric Gate Operators	А
	Manual Gate Operators	Α
	Other Metallic Items	А
	Flap Gates	Α
	Security Fencing	Α
	Intake and Discharge Pipes	Α
	Pressurized Pipe	Α

Monday, April 13, 2009 14:52 Page 9 of 9